Front view -The lack of structural support on the porch pillars and second story.



View of the dilapidated and missing decking on the porch



Interior view of the living area walls and ceiling because of the compromised floor on the second story



Interior view of water damage to the wall and ceiling of bath.

