Existing Brick Manholes to be Replaced



Note the absence of some bricks



City maintenance crews have replaced the top part of these manhole structures, but without the equipment to replace them, the tops have become misaligned with the brick portion of the structures.

Existing Junction Box Near Lone Elm Rd.



North outlet pipe (not shown)

debris builds up in the center of this structure

South outlet pipe (not shown)