Front view of main structure with broken and missing windows



Back deck with compromised support. construction



Interior view of vandalism. Electrical wiring removed,



Interior view of abandon renovations and vandalism.



Exterior view of accessory building with broken & missing windows as well as a dilapidated roof



Interior view of accessory building with ceiling collapsing.



Third retaining wall (20LF X 5FT height and crumbling steps to the accessory building



Retaining wall 1 & 2 on the South side of the main structure to the lower level and walkway to the accessory building



Corner view of the fourth retaining wall on the north side of the main structure approximately 20LF X 5 FT height

