H.C.C.S

17965 Raccoon Rd.

Granby MO

64844

417-592-8429

In this letter an estimated cost for updated repairs and replacement of equipment at the old Library location at 300 South Main Street, Joplin MO.

The estimate includes new condensing units, a rework of the existing air handlers to accommodate the high pressure of the updated condensers.

Replacement of 10 VAV units..

And labor to remove and install the proposed changes.

This is an estimated cost of $350,000.00.

Thank You for considering us for your project.

Travis Wright

Owner H.C.C.S